

Index of FSTs

FST Number	Date	Description
FST001	October 1996	Broadband ADCP Advanced Principles of Operation
FST002	September 1997	Information on Building Your Own Workhorse ADCP Battery Packs
FST003	May 1998	Calculating Absolute Backscatter in Narrowband ADCPs
FST004	August 1999	Using the 305A4205 Hydrophone to Identify the RSSI Scale Factors for Calibrating the Echo Strength Output of an ADCP
FST005	January 2002	Ocean Surveyor/Ocean Observer Power Requirements
FST006	July 2003	Channel Master Expert Commands
FST007	October 2003	Testing Battery Voltage under Load Conditions
FST008	February 2005	GPS Delay Problem with WinRiver
FST009	October 2005	Lowered ADCP to Waves Upgrade
FST010	January 2006	Transforming Windows into a Data Logger
FST011	June 2006	REMUS Bottom Tracking UP&DOWN
FST012	June 2006	Decode PDx Binary Format Data
FST013	September 2006	Compass Calibration
FST014	November 2006	Workhorse to Inductive Modem Setup
FST015	November 2006	300 kHz Narrow Beam Horizontal ADCP with Directional Wave Measurement Capability
FST016	August 2007	Workhorse Mariner Deck Box Triggering
FST017	April 2007	ADCP Backscatter and Suspended Sediment Concentration
FST018	January 2008	NEMO Shore Powered Real-Time Applications
FST019	June 2008	Power Consumption for WorkHorse ADCPs
FST020	July 2008	Lever Arm Correction
FST021	August 2008	WorkHorse Recorder Data Recovery
FST022	February 2009	Integrated NEMO to Sea-Bird Electronics, Inc. IMM Setup
FST023	March 2009	Workhorse to Inductive Modem Setup
FST024	March 2009	N/A - See ICN-128
FST025	April 2009	WorkHorse Triggers Broadband LADCP
FST026	June 2009	Workhorse Pressure Sensor Accuracy
FST027	April 2010	Integrated NEMO Compass Calibration Guide
FST028	February 2011	OS Beamformer Board Replacement
FST029	April 2011	Stability of ADCP Measurements
FST030	May 2011	DVS PIO and DSP Board Replacement
FST031	May 2011	Integrated NEMO to Sea-Bird Electronics, Inc. Inductive Modem Module Setup
FST032	June 2011	How to Check for Ringing in WorkHorse ADCPs
FST033	June 2011	Using the SENA SD1000U Bluetooth Communication Device
FST034	June 2011	Mariner I/O Cable Dry End Connector Assembly
FST035	July 2011	DVS End Cap Interface Board Replacement
FST036	July 2011	WorkHorse End Cap Connector Replacement

Field Service Technical Notes

FST-index

FST Number	Date	Description
FST037	July 2011	DVS Phase I to Phase II Upgrade
FST038	July 2011	Replacing the WH Real-Time Clock Lithium Battery
FST039	August 2011	Replacing the WH Receiver EMI Shield
FST040	August 2011	Testing DVS Post Upgrade of DSP_PIO
FST-041	October 2011	Replacing the WH Receiver Board
FST-042	February 2012	Replacing the WH DSP Board
FST-043	April 2012	Using the SXBlue II-L GPS for OmniSTAR
FST-044	April 2012	Sentinel V Firmware Update Procedure
FST-045	May 2012	Sentinel V Firmware Update for 47_08 and higher
FST-046	July 2012	How to Check for Ringing in RiverRay ADCPs
FST-047	November 2012	NXIC CTD Seapoint Sensor Interface with Gain Settings
FST-048	June 2013	OS150 Temperature Sensor Replacement
FST-049	May 2014	OO-DR Circuit Breaker Upgrade Kit
FST-050	June 2014	OS150 Anode
FST-051	June 2015	V Series End Cap Connector Replacement
FST-052	June 2014	WorkHorse Tilt Sensor Maximum Limit
FST-053	July 2015	WorkHorse Lithium Battery Packs
FST-054	January 2016	Source Level of TRDI ADCP Transducers
FST-055	March 2017	ADCP Sanitization Procedure