




► 6000 Series

AGS Source Energy Connectors - Bolt Air Gun

AGS-6102 • AGS-6104






► 6000 Series


AGS Source Energy Connectors - Bolt Air Gun

AGS-6202 • AGS-6204



WIRING TYPES AGS 6204

AGS 6204			Type A XX04 M	Type B XX04 M	Type C XX04 M	Type D XX04 M
T(-)	Transducer Neg (-)	Black	Pin 1	Pin 4	Pin 1	Pin 4
T(+)	Transducer Pos (+)	Red	Pin 2	Pin 3	Pin 3	Pin 2
S:2	Solenoid 2	Green	Pin 3	Pin 2	Pin 2	Pin 1
S:1	Solenoid 1	Yellow	Pin 4	Pin 1	Pin 4	Pin 3



AGS-6204

Heavy Duty
Recommended for all Bolt Air Guns





► 6000 Series

AGS Source Energy Connectors - Bolt Air Gun

AGS-6254

O-RING 0100-1005

O-RING 0100-1010

WIRING TYPES AGS 6204

AGS 6254			Type A XX04 M	Type B XX04 M	Type C XX04 M	Type D XX04 M
T(-)	Transducer Neg (-)	Green	Pin 1	Pin 4	Pin 1	Pin 4
T(+)	Transducer Pos (+)	Red	Pin 2	Pin 3	Pin 3	Pin 2
S:2	Solenoid 2	Black	Pin 3	Pin 2	Pin 2	Pin 1
S:1	Solenoid 1	Yellow	Pin 4	Pin 1	Pin 4	Pin 3

AGS-6254

Ruggedized for large airguns and extended service life






► 6000 Series

AGS Source Energy Connectors - Sleeve Air Gun

AGS-6302






► 6000 Series

AGS Source Energy Connectors - Sleeve Air Gun

AGS-6312






► 6000 Series

AGS Source Energy Connectors - Sleeve Gun Solenoid

AGS-6322







► 6000 Series

AGS Source Energy Connectors - Sleeve Air Gun

AGS-6402 • AGS-6412






► 6000 Series

AGS Source Energy Connectors - Heavy Duty Sleeve Air Gun

AGS-HD6402 • AGS-HD6412






► 6000 Series

AGS Source Energy Connectors - SSI G & GI Air Gun

AGS-6612




AGS-6612



► 6000 Series

AGS Source Energy Connectors - SSI G & GI Air Gun

AGS-6632






► 6000 Series

AGS Source Energy Connectors - SSI G & GI Air Gun

AGS-6652



Ruggedized for large airguns and extended service life